	50X1	CONFIDENTIAL	REPORT NO
	30/1		50X1
	<u></u>		·
	COUNTRY Czechoslovakia		DATE DISTR. 31 March 1954
,	SUBJECT The S-102 (MIG- Czech Jet Aircr	-15) and S-103 (BIS) raft	NO. OF PAGES 7
ý	DATE OF INFORMATION		REFERENCES:
ė.	PLACE ACQUIRED		
* 3		50X1	
Ne see			
•	TH	HIS IS UNEVALUATED INFORMATIO	DN
		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
	SOURCE		
E0144			
50X1			
	I. GENERAL:		
e ²		raft in the Czechoslovak	
	15 powered by the M C	cions, S-102 and S-103, 05 (which is the Czech do	esignation for the engine
	(this would correspon	lfugal flow turbojet of and to the Soviet RD-45f	engine which is rated
0X1	from hear	say information - is so	the thrust figure given newhat higher). The
	for engine in Bis typ	pe airplane) centrifugal	(Czechoslovak designation flow turbojet engine
	Soviet VK-1 engine, w	static thrust (this engineration of the state of the stat	ne corresponds to the the MIG-15 Bis, of
0X1	2,700 - 2,790 kg. sta	•	
3/(1	and indicated the dif	ferences evident on the	l) of the S-102 (MIG-15) S-103 (MIG-15 Bis).
	Listed below they are):	
		OONFIDENTIAL	
		•	

50X1

50X1

50X1

50X1

50X1

Gunsight

ASP-3N (Old Soviet MIG-15 airplanes had

ASP-31 gunsight)

Fuel capacity

main fuselage tank 1,040 lit.
rear fuselage "U" tank 420 lit.

2 wing drop tanks

250 lit. each

(Note: The larger drop tanks, with additional horizontal tail stabilizing file, could also be used. He did not know its capacity).

Max. level flight speed 1,040 km/hr

C. Aileron Boost Controls:

Source stated that the first MIG-15's delivered from the USSR did not have aileron booster controls. However, the S-102's (MIG-15) built in Czechoslovakia were equipped with aileron 50X1 _Note: booster controls. the M 05 engine then was equipped with an additional hydraulic booster pump which used a red hydraulic fluid.7 50X1 on an airplane with this installation and did not know where the extra booster pump was located. Since the Soviet RD-45f engine accessory section did have an additional drive pad which could possibly be used to drive an extra hydraulic pump, this 50X1 modification appears possible. S-102 aircraft were equipped with booster controls but believed that the majority were so equipped.

D. Vertical Camera Installation:

The S-102 had a vertical camera installation located directly below the pilot. The space was in all aircraft but Source did not know how many aircraft had vertical cameras installed.

E. Armament:

During May-June 1953 several mechanics were sent to the Air Research Institute in Prague to help develop an external bombing installation on the S-102. The project consisted of installing an anti-tank type of bomb (weight or particulars unknown) on the external shackles of the S-102. According to Source this idea had to be abandoned due to damage suffered by the aircraft wing structure during bombing tests. Source had never seen bombs mounted on any S-102 or S-103 aircraft.

and S-103 could carry an external rocket installation. A rocket carrier was mounted on each wing tank shackle and carried rails for launching 16 rockets (total of 32 rockets). They were told this installation was in use on MIG-15's in the USSR. (Source had never seen or heard of such an installation on any S-102 or S-103 in Czechoslovakia. He did not know if it was a cluster or single-spaced rocket arrangement.)

F. Fuel Tanks:

The main fuselage fuel tank of 1,040 lit. capacity was constructed from a rubberized material. The rear "U"-shaped tank of 420 lit. capacity was of light alloy metal construction.

CONFIDENTIAL

50X1

50X1

50X1

The wing drop tanks were constructed from two types of material; light metal and a fiber-bonded material. All S-102 and S-103 airplanes that were delivered from the USSR to Czechoslovakia came equipped with wing drop tanks constructed from a fiberbonded material. The bonded construction was composed of several layers of cloth. (Source referred to the paper as Tvrzeny paper.) Total thickness of the tank walls was one centimeter. The tanks were made up of several circular cross sections bonded together. Source did not know how the sections were joined together. A strip of cloth was bonded around the exterior of each joint.

These fiber tanks leaked at the wing attachment points and were discarded in favor of the Czechoslovak-made light metal tanks.

Engine:

The engines installed in the S-100 was designated M 05 (this appears to be equivalent to the Soviet built RD-45f). (This same Czechoslovak engine designation appeared on a bill of materials dated 5 February 1952 obtained from the Jan Sverma Factory in Prague, manufacturing the engine, 50X1 · Component manufacture and assembly is done at Letnany. Assembly of complete engines is performed at Motorlet, Prague-Jinonice. The engines are then sent to Stara Boleslav for testing. (Accepted production engines are then shipped to the Vodochody Plant for installation in the S-102 airframe).

The only performance data figure of 2,450 kg. at 12,300 rpm. was a maximum thrust $^{50 exttt{X1}}$

Accessories included engine starter, generator, hydraulic pump (in some cases an extra hydraulic pump for aileron booster control). Source did not know any of the part designations. An engine fire extinguisher system such as used for the Soviet RD-45f was also included. Source had never heard of the Soviet designation for the MIG-15 or MIG Bis engine (RD-45f and VD-1).

The engine lines were coded in the following way:

Hydraulic pressure gray (also banded) Fuel yellow 011 brown Air pressure black Fire extinguisher red

This is the same engine color coding procedure followed by the Soviets.

50X1

I. Fuel and Oil:

Η.

Fuel used (for M-05 and M-06 engines) was a kerosene type (strawcolored) designated LRX-52. sented "air" (referring to air force, etc.) and the "R" meant "for jet aircraft". The fuel was a mixture of kerosene with an additive of LM-120 oil plus stearic acid (ratio unknown).

CONFIDENTIAL

Declassifie	d in P	eart - Sanitized Copy Approved for Release @ 50-Yr 2013/07/12 : CIA-RDP82-00046R0003002500	16-4			
		CONFIDENTIAL 50X1				
50X1		Oil used was designated LM-100 and LM-120. (A change to winter grade oil was made during the period 15 October - 15 November; change to summer oil was made during the period 15 March - 15 April. (LM-100 or LM-120) referred to summer or winter).				
	J.	Production of S-102 Aircraft:				
50X1	Source stated that S-102 aircraft produced in Czechoslovakia were being shipped to Rumania, Hungary, Poland, and Bulgaria. military pilots who were ferrying S-102 aircraft to these countries. They recounted an incident that occurred in December 1953 when 50 S-102 aircraft were being ferried to Rumania. The flight encountered bad weather and they were forced down at Zatec Ten aircraft remained at Zatec and were turned					
50X1 50X1		over to a squadron; the other 40 were later ferried to Rumania Zatec was to receive 10 aircraft at a future date, this opportunity was taken to leave 10 aircraft there and "fill the order"). Source did not know if such large flights were common or how many aircraft had been shipped out of Czechoslovakia. He knew of one other case when six S-102 aircraft were to be sent to Poland but defects were discovered and they were not shipped out				
III.	CS-	102 (U-MIG-15):				
	The CS-102 was the Czechoslovak designation for the Soviet U MIG-15 trainer (engine installation conformed to the RD-45f). There were some differences from the S-102 such as:					
	a.	The CS-102 was equipped with the ARK (automatic radio compass) installation, which the S-102 did not have.				
	b.	Additional installation of a radio altimeter.				
	c.	Armament changed to only one gun (Source did not know what type or where located).				
50X1	out for	of the above features would help the student pilots in checking in the newer S-103 (MIG-15 Bis) since the Bis is better equipped instrument flying, due to the addition of the ARK and radio imeter equipment. All CS-102 aircraft were of Soviet origin.	X 1			
IV.	<u>S-103 (MIG-15 Bis)</u> :					
	The Soviet MIG-15 Bis (Soviet designation) was designated by the Czechs as the S-103 (there was no CS-103 trainer version). The S-103 was equipped with a centrifugal flow turbojet engine designated M-06 by the Czechs. (Maximum thrust was 2,650- 50X1 2,750 kg., which would correspond to the Soviet VK-1 which is known to be in the MIG-15 Bis). See paragraph I and Encl. 1 for further					
50X1 50X1	such	ails on the S-103. Source had never heard of IFF 503 any antennas on the S-102 and S-103 that would indicate an an installation one radio altimeter enna unit on the right wing, none on the left wing - such as the -15 Bis is known to have.)	Λ Τ			

A. Wing Drop Tanks:

The MIG-15 Bis aircraft which were sent from the USSR were first shipped with a drop tank larger than the 250 lit. tank of the MIG-15. The approximate dimensions were three meters long, one-half meter maximum diameter. The tank was also distinguished by the addition of a horizontal stabilizing fin at the tail end

CONFIDENTIAL

		CONFIDENTIAL - 6 -	
		of the tank /see Encl. 17. These tanks were made of a bonded fiber composition (same as the S-102 tanks sent from the USSR) /see paragraph $\overline{17}$).	
		The fiber tanks leaked and as a result the 250 lit. metal tanks (as used for the S-102) were substituted. a metal version of the new and larger drop tank. No fiber tanks were made in Czechoslovakia.	50X1
	в.	Production of S-103 Aircraft:	
V		The first MIG-15 Bis parts (crated) arrived from the USSR in the summer of 1951. Engines were also Soviet built. These aircraft (number unknown) were assembled by Czech airmen at Mlada. In addition, mechanics from all four fighter regiments of the Headquarters 4th Fighter Division learned the assembly of the MIG-15 Bis at Mlada.	
50X1		In December 1953, some mechanics went to the Rudy Letov plant in Prague to pick up some S-102's. They reported that parts for the S-103 were being made there at that time.	50X1
50X1		In January-February 1954, Let-Ol in Kunovice upper sections or the vertical stabilizer for the S-103 were being made there. The ARK radio compass unit is being made at the Tesla Electronic Plant in Kolin.	50X1
		The M-06 turbojet engine for the S-103 is being made at Prague-Letnany. All engine assembly, is being done at the Motorlet Plant at Prague-Jinonice. The engines are then sent to Stara Boleslav for testing.	50X1
	· .	The final assembly of the engine in the S-103 is done at Vodochody. Acceptance test flights are also conducted at Vodochody. Source has no production figures.	
٧.			
50X1			
ENCI	Losui	RE:	

Declassified in Part - Sanitized Copy Approved for Release @ 50-Yr 2013/07/12 : CIA-RDP82-00046R000300250016-4

A three-view drawing of the S-102 (MIG-15) and Indicated Differences Evident on the S-103 (MIG-15 Bis).

CONFIDENTIAL

